

portion service parts catalogue

Page 2	Portion chair with two arms on a stainless steel sled base
Page 3	Portion chair with two arms on wooden legs
Page4	Portion chair with right arm on a stainless steel sled base
Page 5	Portion chair with right arm on wooden legs
Page 6	Portion chair with left arm on a stainless steel sled base
Page 7	Portion chair with left arm on wooden legs
Page 8	Portion chair with no arms on a stainless steel sled base
Page 9	Portion chair with no arms on wooden legs
Page 10	Portion single stool on a stainless steel sled base
Page 11	Portion single stool on wooden legs
Page 12	Portion 2 seat with two arms on a stainless steel sled base
Page 13	Portion 2 seat with two arms on wooden legs
Page 14	Portion 2 seat bench on a stainless steel sled base
Page 15	Portion 2 seat bench on wooden legs
Page 16	Portion 2 seat with right arm on a stainless steel sled base
Page 17	Portion 2 seat with right arm on wooden legs
Page 18	Portion 2 seat with no arms on a stainless steel sled base
Page 19	Portion 2 seat with no arms on wooden legs
Page 20	Portion 2 seat with left arm on a stainless steel sled base
Page 21	Portion 2 seat with left arm on wooden legs
Page 22	Portion 3 seat with two arms on a stainless steel sled base
Page 23	Portion 3 seat with two arms on wooden legs
Page 24	Portion 3 seat bench on a stainless steel sled base
Page 25	Portion 3 seat bench on wooden legs
Page 26	Portion 3 seat with right arm on a stainless steel sled base
Page 27	Portion 3 seat with right arm on wooden legs
Page 28	Portion 3 seat with no arms on a stainless steel sled base
Page 29	Portion 3 seat with no arms on wooden legs
Page 30	Portion 3 seat with left arm on a stainless steel sled base
Page 31	Portion 3 seat with left arm on wooden legs
Page 32	Portion chaise with right arm on a stainless steel sled base
Page 33	Portion chaise with rightt arm on wooden legs
Page 34	Portion chaise with left arm on a stainless steel sled base
Page 35	Portion chaise with left arm on wooden legs
Page 36	Portion service parts index

naughtone


Unit D Knaresborough Tech Park, Knaresborough, HG58LF

www.naughtone.com T: +44 1423 816500 E:sales@naughtone.com

Company reg number: 5285557



chair with two arms on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chair with two arms on a stainless steel sled base	POR12ASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair 2 arms (This part must be returned for servicing)	POR12ANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







chair with two arms on wooden legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chair with two arms on wooden legs	POR12AWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair 2 arms (This part must be returned for servicing)	POR12ANOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







chair with right arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chair with right arm on a stainless steel sled base	POR1RASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair right arm (This part must be returned for servicing)	POR1RANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







chair with right arm on wooden legs




	Portion chair with right arm on wooden legs	POR1RAWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair right arm (This part must be returned for servicing)	POR1RANOBASE	1
02	Portion wooden leg front (Multiple options)	Pickfromindex line 5-6	2
03	Portion wooden leg back (Multiple options)	Pickfromindex line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







chair with left arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chair with left arm on a stainless steel sled base	POR1LASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair left arm (This part must be returned for servicing)	POR1LANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15





chair with left arm on wooden legs



	Portion chair with left arm on wooden legs	POR1LAWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair left arm (This part must be returned for servicing)	POR1LANOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15

FINISHED ITEM No.

 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$




FINISHED ITEM DESCRIPTION





chair with no arms on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chair with no arms on a stainless steel sled base	POR1NASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair right arm (This part must be returned for servicing)	POR1NANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







chair with no arms on wooden legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chair with no arms on wooden legs	POR1NAWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chair no arms (This part must be returned for servicing)	POR1NANOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







single stool on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion single stool on a stainless steel sled base	POR1STSL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion single stool (This part must be returned for servicing)	POR1STNOBASE	1
02	Portion bench sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	4
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







single stool on a solid oak legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion single stool on wooden legs	POR1STWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion single stool (This part must be returned for servicing)	POR1STNOBASE	1
02	Portion wooden bench leg	Pick from index line 1-2	4
03	M8 X 75 dowel screw	M8X40TXBUT	4
04	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	15







2 seat with two arms on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat with two arms on a stainless steel sled base	POR22ASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat 2 arms (This part must be returned for servicing)	POR22ANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21





2 seat with two arms on wooden legs




Portion 2 seat with two arms on wooden legs		
Formon 2 sear will two drints on woodernegs	POR22AWD	
COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
Portion 2 seat 2 arms (This part must be returned for servicing)	POR22ANOBASE	1
Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
M8 X 75 dowel screw	M8X75DOWELSCREW	2
8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
M8 X 40 TX40 button screw	M8X40TXBUT	4
Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21
	Portion 2 seat 2 arms (This part must be returned for servicing) Portion wooden leg front (Multiple options) Portion wooden leg back (Multiple options) M8 X 75 dowel screw 8 X 100 Heco topix countersunk wood screw M8 X 40 TX40 button screw Portion wooden leg bracket 9005 black	Portion 2 seat 2 arms (This part must be returned for servicing) Portion wooden leg front (Multiple options) Pickfromindexline 5-6 Portion wooden leg back (Multiple options) Pickfromindexline 3-4 M8 X 75 dowel screw M8X75DOWELSCREW 8 X 100 Heco topix countersunk wood screw M8X40TXBUT Portion wooden leg bracket 9005 black PORWDLEGBRACKETBLACK







2 seat bench on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat bench on a stainless steel sled base	POR2BENSL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat bench (This part must be returned for servicing)	POR2BENNOBASE	1
02	Portion bench sled leg	PORBENSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	4
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21





2 seat bench on a solid oak legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat bench on wooden legs	POR2BENWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat bench (This part must be returned for servicing)	POR2BENNOBASE	1
02	Portion wooden bench leg	Pick from index line 1-2	4
03	M8 X 75 dowel screw	M8X40TXBUT	4
04	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21







2 seat with right arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat with right arm on a stainless steel sled base	POR2RASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat right arm (This part must be returned for servicing)	POR2RANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21





2 seat with right arm on wooden legs



	Portion 2 seat with right arm on wooden legs	POR2RAWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat right arm (This part must be returned for servicing)	POR2RANOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21

FINISHED ITEM No.

 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$




FINISHED ITEM DESCRIPTION





2 seat with no arms on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat with no arms on a stainless steel sled base	POR2NASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat no arms (This part must be returned for servicing)	POR2NANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21





2 seat with no arms on wooden legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat with no arms on wooden legs	POR2NAWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat no arms (This part must be returned for servicing)	POR2NANOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21







2 seat with left arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat with left arm on a stainless steel sled base	POR2LASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat left arm (This part must be returned for servicing)	POR2LANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21





2 seat with left arm on wooden legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 2 seat with left arm on wooden legs	POR2LAWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 2 seat left arm (This part must be returned for servicing)	POR2LANOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	21





3 seat with two arms on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 3 seat with two arms on a stainless steel sled base	POR32ASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 3 seat two arms (This part must be returned for servicing)	POR32ANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	33





3 seat with two arms on wooden legs




 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$



 $product identification \, label \, is \, located \, here, please \, reference \, this \, number \, when \, you \, require \, a \, replacement \, part \, and \, replacement \, and \, repla$

3 seat bench on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 3 seat bench on a stainless steel sled base	POR3BENSL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 3 seat bench (This part must be returned for servicing)	POR3BENNOBASE	1
02	Portion bench sled leg	PORBENSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	4
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	33





3 seat bench on a solid oak legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 3 seat bench on wooden legs	POR3BENWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 3 seat bench (This part must be returned for servicing)	POR3BENNOBASE	1
02	Portion wooden bench leg	Pick from index line 1-2	4
03	M8 X 75 dowel screw	M8X40TXBUT	4
04	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	33







3 seat with right arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 3 seat with right arm on a stainless steel sled base	POR3LASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 3 seat right arm (This part must be returned for servicing)	POR3RANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	33





3 seat with right arm on wooden legs



 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$




 $product identification \, label \, is \, located \, here, please \, reference \, this \, number \, when \, you \, require \, a \, replacement \, part \, and \, replacement \, and \, replacem$



regional compliance labels located on a swing tag here if applicable

3 seat with no arms on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 3 seat with no arms on a stainless steel sled base	POR3NASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 3 seat no arms (This part must be returned for servicing)	POR3NANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	33





3 seat with no arms on wooden legs




 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$



 $product identification \, label \, is \, located \, here, please \, reference \, this \, number \, when \, you \, require \, a \, replacement \, part \, and \, replacement \, and \, replacem$



3 seat with left arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion 3 seat with left arm on a stainless steel sled base	POR3LASL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion 3 seat left arm (This part must be returned for servicing)	POR3LANOBASE	1
02	Portion sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	33





3 seat with left arm on wooden legs




 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$



 $product identification \, label \, is \, located \, here, please \, reference \, this \, number \, when \, you \, require \, a \, replacement \, part \, and \, replacement \, and \, replacem$



chaise with right arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chaise with right arm on a stainless steel sled base	PORCHRSL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chaise right (This part must be returned for servicing)	PORCHRNOBASE	1
02	Portion chaise sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	26





chaise with right arm on wooden legs




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chaise with right arm on wooden legs	PORCHRWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chaise right (This part must be returned for servicing)	PORCHRNOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	26







chaise with left arm on a stainless steel sled base




	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chaise with left arm on a stainless steel sled base	PORCHLSL	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chaise left (This part must be returned for servicing)	PORCHLNOBASE	1
02	Portion chaise sled leg	PORSLLEG	2
03	M8 X 40 TX40 button screw	M8X40TXBUT	6
04	Felt pad adhesive back 45mm dia	FELTPAD45D	4
05	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	26





chaise with left arm on wooden legs



	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Portion chaise with left arm on wooden legs	PORCHLWD	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Portion chaise left (This part must be returned for servicing)	PORCHLNOBASE	1
02	Portion wooden leg front (Multiple options)	Pick from index line 5-6	2
03	Portion wooden leg back (Multiple options)	Pick from index line 3-4	2
04	M8 X 75 dowel screw	M8X75DOWELSCREW	2
05	8 X 100 Heco topix countersunk wood screw	8X100HECOTOPIXCS	4
06	M8 X 40 TX40 button screw	M8X40TXBUT	4
07	Portion wooden leg bracket 9005 black	PORWDLEGBRACKETBLACK	2
08	No 30 buttons *fabric must be specified *part serviced on site by naughtone engineer	NO30BUTTON	26





portion index

INDEX REF No.	COMPONENT ITEM No.	COMPONENT ITEM DESCRIPTION.
1	PORWDBENLEGOAK	Portion wooden bench leg oak
2	PORWDBENLEGWAL	Portion wooden bench leg walnut
3	PORWDLEGBACKOAK	Portion wooden leg back oak
4	PORWDLEGBACKWAL	Portion wooden leg back walnut
5	PORWDLEGFRONTOAK	Portion wooden leg front oak
6	PORWDLEGFRONTWAL	Portion wooden leg front walnut