

## busby service parts catalogue

Page 2 Busby chair left

Page 3 Busby chair right


Page 4 Engineering Changes

naughtone Unit D Knaresborough Tech Park, Knaresborough, HG58LF

www.naughtone.com T: +44 1423 816500 E:sales@naughtone.com

Company reg number: 5285557






	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Busby chair left	BUSL	
,			
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Busby chair left (This part must be returned for servicing)	BUSLNOBASE	1
02	30PTFEGLIDE30mm clear PTFE + EVA glide ref: 59E.078950	30PTFEGLIDE	4
03	No6 X 3/4 Flange Pozi Self Tapping Screw Zinc	NO6FLANGEPOZI	4
04	Busby bolster cushion (Covering fabric must be specified)	BUSBOLSTERCUSION	1
05	Busby 18" fibre scatter cushion (Covering fabric must be specified)	BUSSCATTERCUSION	1

 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$ 











	FINISHED ITEM DESCRIPTION	FINISHED ITEM No.	
	Busbychairright	BUSR	
	COMPONENT ITEM DESCRIPTION.	COMPONENT ITEM No.	QUANTITY.
01	Busby chair right (This part must be returned for servicing)	BUSRNOBASE	1
02	30PTFEGLIDE30mm clear PTFE + EVA glide ref: 59E.078950	30PTFEGLIDE	4
03	No6X3/4FlangePoziSelfTappingScrewZinc	NO6FLANGEPOZI	4
04	Busby bolster cushion (Covering fabric must be specified)	BUSBOLSTERCUSION	1
05	Busby 18" fibre scatter cushion (Covering fabric must be specified)	BUSSCATTERCUSION	1

 $further information for all our products can \ be \ downloaded \ from \ the \ website \ www.naughtone.com.$ 







## engineering changes

ECO REF	FINISHED ITEMS AFFECTED	DATE CHANGED	
00004	BUSL&BUSR	31/07/2017	
	DESCRIPTION OF ENGINEERING CHANGE	OLD Component item No.	NEW Component item No.
	Changed glide and fixing across all the Busby range	15793001	30PTFEGLIDE
	Supply NEW style glide and fixing for all historic and new orders	15801801 8X34CSWOODSCREW	NO6FLANGEPOZI